



RevNo	Revision note	Date	Signature	Checked
A	ORIGINAL	19/12/03		



SLOPE ON TOP OF POSTS AS DIRECTED BY CLIENT  
NORMAL ALIGNMENT IS WITH THE SLOPE TO THE FRONT



**Outdoor Structures Australia**  
Practical solutions that enhance community design projects

1300 762 443

Date	OUTDOOR STRUCTURES AUSTRALIA			Description
29/01/2003	INSTALLATION INSTRUCTIONS			STANDARD BOLLARD
Drawn				
E.M.S.	Scale	Job No	Drawing No	
Approved	N.T.S.	OSA	TBPBI	
E.M.S.				